


WIRING DIAGRAM FOR HIPPO HOT WATER PRESSURE CLEANER






PROJECT: HIPPO TST 400V-50Hz Three Phase	PAGE 2
	OF 2
ENGINEER: Matteo Botti	1 <>
DATE: 24-11-2009	

## List of components

Tag (-)	Code	Description	Constructor	Page	Column
Y1	50.000.024	Solenoid Valve		2	4
K1	70.000.014	Thermostat		2	4
S1	40.000.006	Flow Switch		2	4
S2	70.000.022	Gasoil Float		2	5
H1	70.000.116	Orange Light		2	5
SR1	70.000.011	Electronic Board		2	5
H2	70.000.016	Green Light		2	5
F1	70.000.074	Fuse 32A		2	5
T1	70.000.019	HT Transformer		2	5
A1				2	6
S3	70.000.035	Pressure Switch		2	6
M1	50.000.221	Burner Motor		2	6
Q1	70.000.015	Burner Switch		2	7
T2	70.000.010	Transformer 0-24V		2	7
Q2	70.000.045	Start Switch		2	7
F2	70.000.060	Fuse 3.1A		2	7
K2		Contactore		2	7
Q3	70.000.008	Magnetothermic Switch		2	8
M2		Three Phase Motor		2	8